

MANUFACTURER'S INSTRUCTION AND INFORMATION

Manufacturer: ROCK SAFETY Kft
Address: 5100 Jászberény, Nagykátai út 10.
Designation of PPE: High visibility vest
Identifiers: BLINKIT-O (fluorescent orange)
 BLINKIT-Y (fluorescent yellow)

Performance levels of the PPE:

High visibility clothing

The protective vest meets the requirements of the standard MSZ EN ISO 20471:2020 (EN ISO 20471:2013/A1:2016).



MSZ EN ISO 20471:2020
EN ISO 20471:2013/A1:2016

Classified according paragraph 4.1. (area of high visibility materials): **Class 2**

(For size M the reflective stripe is 60 mm wide, for size L, XL, 2XL, 3XL and 4XL it's 50 mm wide)

Meaning of CE-Marking:



The protective garment meets the essential requirements of Regulation (EU) 2016/425 of the European Parliament and of the Council.


Notified Body (performed the EU type-examination and performs the inspection):

INNOVATEXT Textilipari Műszaki Fejlesztő és Vizsgáló Intézet Zrt.

Address: 1103 Budapest, Gyömrői út 86. Identification No.: 1523

Certificate No. of EU Type-Examination Certificate: **B-120/2021**

Size selection:



The size is specified with the size ranges indicated on the protective vest by the symbol prescribed in the standard MSZ EN ISO 13688: 2013. Data are in cm.

Garment size							
Code letter	M	L	XL	XXL	XXXL	XXXXL	
Height	154-178	162-186	162-186	170-194	170-194	170-194	
Bust measurement	94-102	102-110	110-118	118-129	129-135	135-147	
Product size							Tolerance (cm)
Back length	70	72	72	74	74	74	± 1
Half width (closed)	60	64	68	72	76	82	± 1

Used materials for protective garment:

Background material: Raw material composition: 100% polyester. Colour: fluorescent orange/ fluorescent yellow, Mass per unit area: 125 g/m².

Accessories: sewing thread, reflective stripe, velcro.

The base material and the accessories do not contain ingredients which are known or suspected to be harmful to health (e.g causes allergies). The protective clothing meets the requirements of the MSZ EN ISO 13688:2013 standard in term of harmlessness.

Treatment, cleaning:

Washing: In a particularly gentle way, at a temperature at or below 40 °C in a solution containing synthetic detergent, wash inside out. Do not wash together with clothes made of other materials.

Bleaching: Do not handle with soaking and detergent that contains bleaching agent.

Flushing: At a temperature close to the washing, and then in cold water.

Drying: After spin-drying for a normal time, suspended at room temperature.
Do not dry in a tumble drying.

Ironing: Do not iron.

Chemical cleaning: Do not clean with chemicals.

Care symbols:

It can be cleaned to 25 times.

The specified maximum number of cleaning cycles is not the only factor that affects the life of the protective equipment. The life-span depends on use, care, storage, etc. too.

Repairment, maintenance:

The condition of the protective clothing should be checked regularly. If the material or fasteners are damaged, it must be repaired or discarded. It is recommended that the repair should be performed by the manufacturer. Correction of the protective clothing can only be done from the base material. It is forbidden to change the design of the protective clothing compared to the one, which's approved during the EU type examination (e.g to put a print or label on the outside).


Book of instruction:

- Protective clothing should be used in only those areas, where its protective ability is sufficient. To be taken into account during use, that the working conditions are generally different from those used in its examination.
- The protective vest must be worn closed, because this is the only way to provide adequate protection.
- The condition of the protective clothing must be checked before use. Damaged protective clothing (e.g with a hollow, a torn, heavily faded surface), faded or contaminated protective equipment does not provide adequate protection and should not be used. If it becomes damaged during use or the high visibility parts of the PPE (fluorescent or reflective parts) become contaminated, the use of protective clothing shall be stopped immediately. Work shall only be carried out in undamaged protective clothing.
- Use and treatment of the protective clothing must comply with the requirements of regulation 65/1999 (XII. 22.) EüM

Storage:

Store in a dry, well-ventilated place, hung on clothes hangers or wrapped in plastic packet, folded loosely.

Other information:

- The protective clothing ergonomically satisfies the requirements of MSZ EN ISO 13688:2013.
- The label(s) containing the marking and the CE marking must not be removed from the protective clothing.
- The  symbol on the label of protective clothing indicates the existence of this informant and the need to study it.
- The EU Declaration of Conformity is annexed to this information document.